AGENDA ITEM E. NEW BUSINESS

ITEM 1 – Tide View Heights No. 2.

KPB File No.	2021-088
Plat Committee Meeting:	July 12, 2021

STAFF REPORT - ADDENDUM

After the staff report was prepared, the surveyor submitted a request for an exception to KPB 20.40.100 Soils Analysis and report.

EXCEPTIONS REQUESTED:

C. KPB 20.40.100 Soils analysis and report. (for proposed Lot 1A)

<u>Surveyor's Discussion</u>: I am requesting an exception to the requirement for soils investigation for Lot 1A for this replat. There was a gravel pit across Ames Dr., the bluff in the front of the lot does indicate a high water table, and the resulting lot will still have more than the required 20,000 square feet for original and replacement wastewater disposal area.

<u>Staff Discussion</u>: Lot 1A will be decreasing by 21,000 sq. ft. The parent plat was recorded in 1972 and a soils analysis report was not completed at that time.

Staff was able to locate a DEC report for parent Lot 1 from 1980. DEC did not approve the water system.

The asbuilt showing the improvements depicts a septic tank and a log crib leach field located to the northeast of the building. The asbuilt shows the log crib to be located more than 58 feet to the northeast from the building. Staff was not able to determine if a new system has been installed since 1980. It appears that the new lot line may encroach on the log crib septic system as shown on the asbuilt survey from 1980.

DEC requires wastewater systems to be at least 50 feet from slopes greater than 25%.

The water well drilling log shows gravel to a depth of 19 feet. Soils analysis reports are required to provide a test pit to ten feet for shallow trench or bed systems and 12 feet for areas where deep trench or seepage pts will likely be used.

Findings:

- 1. There was a gravel pit across Ames Dr.
- 2. The bluff in the front of the lot does indicate a high water table.
- 3. The resulting lot will still have more than the required 20,000 square feet for original and replacement wastewater disposal area.
- 4. Lot 1A will be decreasing by 21,000 sq. ft.
- 5. The parent plat was recorded in 1972 and a soils analysis report was not completed at that time.
- 6. Staff was able to locate a DEC report for parent Lot 1 from 1980.
- 7. DEC did not approve the water system in 1980.
- 8. The asbuilt showing the improvements depicts a septic tank and a log crib leach field located to the northeast of the building.
- 9. The asbuilt shows the log crib to be located more than 58 feet to the northeast from the building.
- 10. Staff was not able to determine if a new system has been installed since 1980.
- 11. It appears that the new lot line may encroach on the log crib septic system as shown on the asbuilt survey from 1980.
- 12. The water well drilling log shows gravel to a depth of 19 feet.

Staff reviewed the exception request and does not recommend approval based on findings 4, 5, 8, 9, 10, 11.

Staff recommends the Committee select the findings they determine are applicable, make additional findings if needed, tie the findings to the following standards, and vote on the exception in a separate motion.

Unless prohibited under this title, the commission (committee) may authorize exceptions to any of the requirements set forth in this title. Application for an exception shall present the commission (committee) with substantial evidence, justifying the requested waiver or exception stating fully the grounds for the application and the facts relied upon. All exceptions must be requested and granted at the time of preliminary plat approval. Exceptions may not be requested with a final plat submittal.

The commission (committee) shall make findings of fact meeting the following standards before granting any exception:

- 1. That special circumstances or conditions affecting the property have been shown by application;
- 2. That the exception is necessary for the preservation and enjoyment of a substantial property right and is the most practical manner of complying with the intent of this title;
- 3. That the granting of the exception will not be detrimental to the public welfare or injurious to other property in the area in which said property is situated.

Staff recommendation: place notes on the final plat indicating any exceptions granted by the Plat Committee with the meeting date.

END OF STAFF REPORT ADDENDUM

· DEPT. OF ENVIRONMENTAL CONSERVATION

JAY S. HAMMOND, GOVERNOR

P.O. BOX 1207 SOLDOTNA, ALASKA 99669

June 2, 1980

FILED 12/31/80

Mr. Edward Ambarian Route 3 Kenai, AK 99611

TF M

Re: Lot 1, Caro Subdivision

Dear Mr. Ambarian:

This is in response to the conditional approval of your water system for the above referenced lot.

KENAJ FIELD OFFICE

According to our records the improvements were to have been completed by June 1, 1980, in order for this system to be approved by this department.

At this time we have not received any indication that these improvements were made and therefore cannot approve the system.

In the event these improvements were completed and this information not conveyed to this office, please notify us immediately so that we may take further appropriate action.

If you have any questions regarding this matter please feel free to contact this office at 262-5210.

Sincerely,

Mike Luck

Environmental Field Officer

rms cc: Alaska Statebank/Lujean

DEPT. OF ENVIRONMENTAL CONSERVATION

JAY S. HAMMOND, GOVERNOR

KENAI FIELD OFFICE

P. O. BOX 1207 SOLDOTNA, ALASKA 99669

March 17, 1980

Re: Lot 1, Caro Subdivision

Dear Mr. Ambarian:

This may be considered a conditional approval of your water system.

The system as it currently exists is somewhat inadequate and can only be approved when the following condition(s) is/are met no later than 6/1/80.

1) The well casing must be extended to a height of at

least 1 foot above ground surface.

2) A pitless adapter should be installed on the well

casing.

3) The well pit must be filled in.

Please notify this office when the improvements have been conducted so that we may move towards final approval of the system.

If you have any questions regarding this matter, or if we can offer you assistance or advice please feel free to contact this office at 262-5210.

Sincerely,

Mike Luck Environmental Field Officer


rms

Inspected By: Lucia 80-IT-3 7100 Date: ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION Inspection Report For On-Site Individual Sewage And Water Systems GENERAL INFORMATION MBOINISION - BOOK 24, PAGE 372, KENAI KEWRO, DIST. Legal Description: LDT LARD Directions to Site: BEAVER LOOP, TURN ON AMES Rd Applicant Name, Address, and Telephone: EDWARD AMBARIAN ROUTE 3 KEUAI AK 99611 183-3656 OFFICE Realtor and Firm: Lending Institution: ALASKA STATABAUK NIA General Contractor: NIA Lot Owner: Lot Size: 2.4 a(rci House Type: TRAME No. of Bedrooms: SITE DATA SEE ATTACHED LOG WELL _ Well Driller: FRANK KRAXBERGER 8-11-19 Date: Size Casing: 6"\$8" Depth: SA Depth to Water: Yield: (Attach Well Log if Available) Well type: ARTE (IAN -Date Water Sample Taken: 3-12-1980 Results: SATISFACTONY. ATTACHED REPORT DISPOSAL SYSTEM Sewage Sys. Installer: (JJTRJGTIJL Date: Sewer-Septic Tank Type: Size: 1000 GALLOW) Absorption Sys. Type: Size: 10 XIO XIO LDG CRIB Pipe Type: TAM House To SEPTIC LAUR & CRIB- CAST IRON Size: Soils-General Profile: 6000 CIRAVR-SEF SKETCH

Include a site diagram to show the spatial relationship of the on-site water and sewer facilities to the property lines, house foundation, driveway, roads, adjacent property developments, etc. (Use other side if necessary)

SEE ATTACHED SKETCH

WATER WELL DRILLERS LOG. Drilling Co. Frank Kraxberger Drilling DO NOT FILL IN Rt 2 Soldotna, Ak. 99669 USGS No. Ph. 262-4720 Driller Area Well Owner July - CARO Use of Well Location (address of: Township, Range, & Section (if known); distance from road: (amen (id) to sure). Bener down Size of Casing & Depth of Hole 158 feet. Cased to 158 feet. Static water level (feet (above) (below) land surface. Finish of well (check one) Open end (1): Screen (): Perforated (). Describe screen or perforations: Well pumping test at 3() gallons per (hr) (min) for hours with feet of drawdown from static level. 43.34 1.06 Remarks & Luck) Consul Date completed 22 2 WELL LOG Depth in feet from Give details of formations penetrated, size of material, ground surface color, and hardness. 19 to QAAN to 3 In X to to 5 to 76. to 11.2 12 to 126 2 26 to 134 A 4 to 153 53 to 157 NB 57 to 1.58 LANA A 0.0.24 10 to 20



Huff, Scott

From: Sent:	Russell, Pamela J (DNR) <pamela.russell@alaska.gov> Tuesday, July 6, 2021 10:32 AM</pamela.russell@alaska.gov>
То:	Huff, Scott
Cc:	Blackwell, Jack D (DNR); Beutel, Dan E (DNR); cpadgettak@gmail.com
Subject:	<external-sender>Tide View Heights Plat-Padgett Conservation Easement</external-sender>

CAUTION: This email originated from outside of the KPB system. Please use caution when responding or providing information. Do not click on links or open attachments unless you recognize the sender, know the content is safe and were expecting the communication.

Good Morning Scott,

State Parks has reviewed the conservation easement on Kenai Peninsula parcel 04904098. It has been determined that you can add property into the conservation easement agreement, but you cannot take away. I have also reached out to the landowners and once the plat and title information has been completed, they will be drafting an addendum to the current conservation easement agreement to add the additional property.

Let me know if you need anything else.

Thanks again for catching this.

Pamela Russell Div. of Parks and Outdoor Recreation Natural Resource Specialist III 514 Funny River Road Soldotna, AK 99669 907-714-2471