


MM 91-21



SURVEYORS CERTIFICATE


I hereby certify that I am a Registered Land Surveyor and that this plat represents a survey made by me or under my direct supervision and the monuments shown hereon actually exist as described and that the dimensions and other details are correct to the best of my knowledge.

Date 6-6-97 Roger W. Imhoff
Roger W. Imhoff LS 5780

97-27
RECORDED - FILED
HOMER REC DIST 20
Date 6/9 19 97
Time 8:40 AM
Requested by
Roger Imhoff
PO Box 2588
Homer Ak 99603

NOTES

1. Found a rotted spruce stob, 10" long and 3" diameter, axe marks visible at tip, with 1 1/2" pipe 0.4 ft east, pipe called for on Plat No. 86-44. Removed spruce stob and replaced with a 2" Aluminum Cap on 5/8" rebar. Removed 1 1/2" pipe.
 2. Found a rotted spruce stob, 12" long and 2" diameter, axe marks visible at tip, with 1/2" rebar alongside, called for on Plat No. 86-44. Removed spruce stob and replaced with a 2" Aluminum Cap on 5/8" rebar. Removed 1/2" rebar.
 3. Slope easement over the easterly 10 ft of Lot 49 is recorded in Bk 131 Page 563.
 4. Utility easment granted to Homer Electric Association in Bk 176 Page 815 over the South 7 1/2 ft. of Lot 49.
 5. Set 2" Aluminum Cap on 5/8" rebar at all lot corners.
- Vicinity Map 1" = 2000 ft



Record of Survey	
Lot 49 Bunnell Subdivision as shown on Plat No. 44-49 Homer Recording District	
Located in the NE 1/4 Section 19, T6S, R13W, SM	
Third Judicial District, Alaska containing 1.089 acres, more or less	
Clients: Jim Daily, et al 11086 Faith Road Yankee Hill CA 95965	Surveyed By: Roger W. Imhoff, RLS PO Box 2588 Homer Ak 99603
Date of Survey 6-06-97	File L 49Bunnl.vcd
Drawn RWI	Scale 1" = 100 ft

This survey does not constitute a subdivision as defined by A.S. 40.15.190.2.